





APC Fittings

BX Straight Connectors Zinc Die Cast




E328238

Applications:

Straight BX connectors are used to join BX flexible conduit to a junction box at 0° angle (straight). Connectors include three drive screws Robertson / Star / slot. Screw 1 1/2" - 1". 2-screws 1 1/4" - 4".

Available in Sizes: 3/8", 1/2", 3/4", 1", 1 1/4", 1 1/2", 2", 2 1/2", 3" & 4".

APC straight BX connectors can be installed where UL listed product is required.

ARTMARK Cat. No.	Size	Standard Carton 	Weight/ Carton (Lbs)	A (mm)	B (mm)	C (mm)	A (")	B (")	C (")
ARTBXSCONN038ZDC	3/8"	500	31	29.0	14.2	13.0	1.14	0.58-0.61	0.51
ARTBXSCONN050ZDC	1/2"	250	21	36.5	19.0	12.5	1.44	0.74-0.95	0.49
ARTBXSCONN075ZDC	3/4"	250	34	40.0	19.7	12.0	1.57	0.88-1.11	0.47
ARTBXSCONN100ZDC	1"	100	17	44.7	17.6	14.2	1.76	1.14-1.38	0.56
ARTBXSCONN125ZDC	1-1/4"	100	26	47.9	25.4	15.0	1.89	1.42-1.65	0.59
ARTBXSCONN150ZDC	1-1/2"	50	17	51.0	26.8	15.5	2.01	1.68-1.94	0.61
ARTBXSCONN200ZDC	2"	40	16	53.0	32.5	15.2	2.09	2.08-2.56	0.60
ARTBXSCONN250ZDC	2-1/2"	10	8	72.5	30.0	22.0	2.85	2.85-3.25	0.87
ARTBXSCONN300ZDC	3"	10	12	82.4	30.0	21.8	3.24	3.33-3.63	0.86
ARTBXSCONN400ZDC	4"	1	1	103.0	37.2	23.0	4.06	4.18-4.58	0.91

11315 NW 36 TER Miami, FL 33178 Tel: (305) 715-9800 Fax: (305) 715-9988

<http://www.artmark.com>

B
X
S
t
r
a
i
g
h
t
C
o
n
n
e
c
t
o
r
s